



Siemens Technical Bulletin STAB11-0066

# ST750 & ST900 Main Firmware Update to PB801 Issue11

5th April 2011

**Product:** ST750 & ST900**Modifications Req:** No**Retrospective Action Req:** No**Priority of Change:** Information only

- ✓ Introduction
- ✓ Scope
- ✓ Procedure
- ✓ Related documents

## Introduction

The ST750/ST900 Firmware (667/1/12801/000) has been updated from PB801 Issue10 to PB801 Issue11.

## Scope

The Main Processor Firmware PB801 Issue11 has now been released to include the facility to lamp monitor Helios CLS (NLM) signals, i.e. without LMF units, using new "LED Phase Driver" cards on the ST750 Controller.

## Procedure

PB801 Issue11 (or later) MUST be fitted in all ST750 controllers fitted with "LED Phase Driver" cards 667/1/33790/00x; see > [667/HB/32921/007](#) for full details.

All other controllers can continue to use the previous issues.

As well as the above, the following features are also available in this release of PB801:

- The problem with the "KDP:2" setting and LED Signals has been fixed
- Corrections and improvements to various handset commands
- SelfTest displays the type of serial I/O card

Refer to > [667/SU/32900/000](#) for the full details of the changes to this firmware.

## Related documents

- > [667/SU/32900/000](#) (issue10 or later)
- > [667/HB/32921/007](#) (issue6 or later)
- > [667/CI/32755/000](#)

**Approved by:** Keith Manston

## Harry Smyth

Senior Product Engineer

Technical Support

### Traffic Solutions

Sopers Lane, Poole, Dorset BH17 7ER

Tel: +44 (0)1202 782027

Mob: +44 (0)7921 242893

Email: > [harry.smyth@siemens.com](mailto:harry.smyth@siemens.com)> [www.siemens.co.uk/traffic](http://www.siemens.co.uk/traffic)

*Committed to quality traffic solutions and service excellence*