




Siemens Energy & Automation, Inc.  
Bellefontaine, Ohio 43311 U.S.A.  
©Siemens Energy & Automation, Inc. 1987

## Installation Instructions

	 <b>DANGER</b>
	<p><b>Hazardous Voltage.</b> Will cause severe injury or death.</p> <p>Turn power off supplying device before installing.</p>
	<b>SAFETY INSTRUCTIONS</b>

NOTE: This instruction outlines the recommended installation procedure.

1. Turn power off supplying device before installing kit.
2. Remove all fuse clips from line and load bases.
3. Mount adaptor assemblies in fuse clip position with 10 - 24 X 1/4" RD. HD. screws and washers as shown in figure above.
4. Mount fuse clips to adaptor assembly as shown in figure above.

NOTE: When reassembling the fuse clip assemblies to the line or load position for a 600 V. installation, if the closed end of the fuse clip spring is facing in towards the fuse blade, remove the spring, rotate 180° and then reassemble to fuse clip.

NOTE: Stamp the assembly area letter adjacent to the interior label.

