

<b>Siemens Technical Action Bulletin No.</b>	<b>STAB21-0127</b>
--	--------------------

<b><u>TITLE</u></b>	<b>Stratos Outstation Firmware Upgrade to 52255 Issue14</b>
---------------------	---

<b>Product</b>	ST900	T400	Cuckoos	Stratos Outstation	ST950	OTU	INSTATION SOFTWARE	OTHER
				▲				

<b>Are Modifications Required?</b>				<b>No</b>			
<b>Retrospective Action Required?</b>				<b>No</b>			
<b>Priority of the Change</b>	URGENT ASAP	ACTION AT NEXT SITE VISIT	ACTION WITHIN 3 MONTHS	ACTION AT NEXT PI	ACTION ONLY IF PROBLEM ARISES	INFORMATION ONLY	
						▲	

<b>Introduction</b>	<p>This bulletin provides notification that the Gemini3/Stratos Outstation Firmware 52255 has now been updated to Issue14 and is available to download from <a href="#">Siemens Traffic</a> website.</p> <p>Along with various maintenance fixes and security enhancements, the new features of this release are:</p> <ul style="list-style-type: none"> <li>• MOVA8 functionality</li> </ul> <p>There is no specific charge for this updated firmware but if a customer wants to upgrade an existing site to include MOVA 8 (including upgrading from a previous version of MOVA), a price for upgrading should be negotiated with the local Field organization.</p> <p>However, Stratos Remote Monitoring functionality is a licensed feature. Normally Stratos Outstations are supplied with a UTMC OTU license which will automatically enable the Monitoring functionality in the controller. If the outstation is not fitted with a license a UTMC License will also need to be purchased.</p> <p>Connection to Stratos requires that the customer has the Stratos Traffic Signals module appropriately enabled. For Remote Monitoring Outstations connected directly to Stratos, the firmware upgrade is completed automatically by the system.</p>
---------------------	--

<b>Scope</b>	Gemini3/Stratos Outstation Firmware upgrades.
--------------	---

<b>Procedure</b>	<p>Please note that you can <b>ONLY</b> upgrade to Stratos Outstation Firmware Iss14 from Iss7 or above. Therefore, if you have &lt;Iss7 then please refer to STAB16-0104 to upgrade to Iss7 first.</p> <p>To upgrade the Stratos Outstation Firmware 52255 to Issue14, you will need the firmware package file <b>REL_52255_14_2_0.pkg</b></p> <p>This is available to download from <a href="#">Siemens Traffic Downloads</a></p> <p>To upgrade the Stratos Outstation Firmware please follow the instructions in the following handbook:</p> <p><a href="#">667/HQ/46000/009</a> - ST950/Stratos Outstation Firmware Upgrade Quick Start Guide</p> <p>Once the upgrade is complete, you should use the <i>System</i> page to verify that it has been uploaded correctly and the Package Version is displayed as: <b>14_2_0</b></p>
<b>Related Documents</b>	<p>667/SU/52255/000 Stratos Outstation Compatibility Handbook Issue 5 (or later) for v14 features.</p> <p>667/HQ/46000/009 ST950/Stratos Outstation Firmware Upgrade Quick Start Guide Issue2 (or later) for instructions on how to upgrade firmware</p>