

Siemens Technical Action Bulletin No.	STAB21-0122
---------------------------------------	-------------

<u>TITLE</u>	ST950 Program Button - Just Tap It
---------------------	-------------------------------------------

Product	ST900	T400	Cuckoos	Street Furniture	ST950	OTU	INSTATION SOFTWARE	OTHER
					▲			

Are Modifications Required?				No			
Retrospective Action Required?				No			
Priority of the Change	URGENT ASAP	ACTION AT NEXT SITE VISIT	ACTION WITHIN 3 MONTHS	ACTION AT NEXT PI	ACTION ONLY IF PROBLEM ARISES	INFORMATION ONLY	
						▲	

Introduction	<p>An issue has been found with the operation of the 'Program' button on ST950 Traffic Controllers.</p> <p>This bulletin has been issued as notification of the issue and provides instructions on how to correctly use the Program Button on the ST950 controllers</p>
---------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Scope	ST950 Program Button
--------------	----------------------

Procedure	<p>The Program button is used during procedures such as loading a new IC4 Configuration, performing a firmware upgrade, and reverting to an earlier Restore Point.</p> <p>If the button is held down, rather than pressed briefly and released, the requested action may be abandoned. So, if the action was performing a firmware upgrade or reverting to a Restore Point, this can (in some cases) cause a corruption that requires the ST950 CPU PCB to be replaced.</p> <p>Therefore, whenever the Program button needs to be pressed, it must be pressed briefly and promptly released. The instant the button is pressed, the Status LEDs on the front of the ST950 CPU PCB reacts immediately to give a clear confirmation that the button press has been recognised and the button should be released.</p> <p>IT MUST NOT BE HELD PRESSED</p>
------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Related Documents	N/A
--------------------------	-----