



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/SIR/QAR15.0019/08	Page 1 of 2
QAR Free Ref. No.:	80229096/80229097/80229098, 80229096A/80229097A/ 80229098A and 80227410/80227411/80227412	Status: Issued
Details of change:	Recertification Audit	Date of issue: 2024-10-29
Location(s) audited:	Siemens AG Oestliche Rheinbrueckenstrasse 50 76187 Karlsruhe Germany	Valid until: 2027-12-04
	Siemens SAS 1 Chemin de la Sandlach 67506 Haguenau Cedex France	Audit date: 2024-10-18
	Siemens Limited Kalwa Works, Thane Belapur Road Navi Mumbai 400708 Maharashtra India	
	Siemens Sensors and Communication Ltd. 117 GuangXian Road, Qixian Ling High-Tech Industrial Zone Dalian 116023 Liaoning Province China	
	Siemens SIMEA Sibui SRL 4 Florian Rieger Street 550018 Sibiu Romania	
	Siemens Canada Limited 1954 Technology Drive Peterborough Ontario K9J 6X7 Canada	
Issuing ExCB:	CSAE - CSA Group Testing UK Ltd	
Manufacturer:	Siemens AG 76181 Karlsruhe	
Location of Manufacturer:	Germany	
Product information:	Pressure Transmitters, Measuring Transducers, Electro Positioners, Temperature Sensors, Gas Analyser, and Flow Transmitter	
Type of protection:	i, d, e, m, nA, t, op, p, h, nC.	
Related QARs:		
GB/SIR/QAR15.0019/00	GB/SIR/QAR15.0019/01	GB/SIR/QAR15.0019/02
GB/SIR/QAR15.0019/03	GB/SIR/QAR15.0019/04	GB/SIR/QAR15.0019/05
GB/SIR/QAR15.0019/06	GB/SIR/QAR15.0019/07	

Related Certificates (manual insertion):



IECEX Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR15.0019/08**

Page 2 of 2

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEX BVS 14.0041X issue: 1	IECEX BVS 14.0104X issue: 2	IECEX BVS 14.0104X issue: 3
IECEX BVS 14.0104X issue: 4	IECEX BVS 14.0104X issue: 5	IECEX BVS 15.0007X issue: 2
IECEX BVS 15.0007X issue: 3	IECEX BVS 15.0007X issue: 4	IECEX BVS 15.0007X issue: 5
IECEX BVS 15.0030X issue: 1	IECEX BVS 15.0030X issue: 2	IECEX BVS 16.0002 issue: 0
IECEX BVS 16.0002 issue: 1	IECEX BVS 16.0041X issue: 0	IECEX BVS 17.0047 issue: 0
IECEX BVS 18.0038X issue: 0	IECEX BVS 18.0038X issue: 1	IECEX BVS 18.0038X issue: 2
IECEX BVS 18.0039U issue: 0	IECEX BVS 18.0039U issue: 1	IECEX BVS 18.0039U issue: 2
IECEX BVS 18.0051U issue: 1	IECEX BVS 18.0051U issue: 2	IECEX BVS 20.0036U issue: 0
IECEX BVS 20.0046U issue: 0	IECEX BVS 22.0010X issue: 0	IECEX BVS 22.0035X issue: 0
IECEX BVS 24.0001X issue: 0	IECEX CML 18.0143X issue: 2	IECEX CML 18.0143X issue: 3
IECEX CML 18.0143X issue: 4	IECEX CML 18.0143X issue: 5	IECEX CML 18.0143X issue: 6
IECEX CSA 12.0016X issue: 4	IECEX CSA 23.0025X issue: 0	IECEX CSA 23.0026X issue: 0
IECEX CSAE 24.0017X issue: 0	IECEX CSAE 24.0018X issue: 0	IECEX DEK 16.0074X issue: 0
IECEX DEK 17.0054X issue: 0	IECEX DEK 17.0054X issue: 1	IECEX DEK 17.0054X issue: 2
IECEX DEK 17.0054X issue: 3	IECEX DEK 19.0025X issue: 0	IECEX DEK 19.0025X issue: 1
IECEX DEK 19.0026X issue: 0	IECEX DEK 19.0026X issue: 1	IECEX DEK 19.0068U issue: 0
IECEX DEK 19.0069X issue: 0	IECEX DEK 19.0070X issue: 0	IECEX DEK 19.0070X issue: 1
IECEX DEK 23.0028X issue: 0	IECEX FMG 16.0037X issue: 0	IECEX FMG 16.0037X issue: 1
IECEX FMG 16.0037X issue: 2	IECEX FMG 17.0004X issue: 0	IECEX FMG 17.0004X issue: 1
IECEX FMG 17.0004X issue: 2	IECEX FMG 17.0004X issue: 3	IECEX FMG 17.0023X issue: 0
IECEX FMG 17.0023X issue: 1	IECEX FMG 17.0023X issue: 2	IECEX FMG 17.0023X issue: 3
IECEX FMG 17.0023X issue: 4	IECEX FMG 17.0023X issue: 5	IECEX KIWA 16.0021X issue: 1
IECEX KIWA 16.0022X issue: 1	IECEX KIWA 19.0028X issue: 0	IECEX KIWA 19.0029X issue: 0
IECEX KIWA 19.0029X issue: 1	IECEX PTB 10.0050X issue: 1	IECEX PTB 11.0010X issue: 2
IECEX PTB 16.0024X issue: 0	IECEX PTB 22.0004X issue: 0	IECEX SEV 14.0003 issue: 2
IECEX SEV 14.0003 issue: 3	IECEX SEV 14.0003 issue: 4	IECEX SEV 16.0003 issue: 2
IECEX SEV 16.0003 issue: 3	IECEX SEV 16.0003 issue: 4	IECEX SEV 16.0008 issue: 2
IECEX SEV 16.0008 issue: 3	IECEX SEV 16.0008 issue: 4	IECEX SIR 05.0031X issue: 14
IECEX SIR 05.0031X issue: 15	IECEX SIR 05.0031X issue: 16	IECEX SIR 08.0107X issue: 12
IECEX SIR 08.0107X issue: 13	IECEX SIR 09.0005X issue: 5	IECEX SIR 09.0083X issue: 6
IECEX SIR 09.0083X issue: 7	IECEX SIR 09.0148X issue: 9	IECEX SIR 09.0148X issue: 10
IECEX SIR 09.0149X issue: 5	IECEX SIR 09.0149X issue: 6	IECEX SIR 10.0067X issue: 3
IECEX SIR 10.0067X issue: 4	IECEX SIR 10.0093X issue: 5	IECEX SIR 10.0093X issue: 6
IECEX SIR 10.0093X issue: 7	IECEX SIR 10.0162U issue: 3	IECEX SIR 10.0162U issue: 4
IECEX SIR 10.0163U issue: 3	IECEX SIR 10.0163U issue: 4	IECEX SIR 10.0163U issue: 5
IECEX SIR 11.0104U issue: 3	IECEX SIR 11.0149X issue: 6	IECEX SIR 11.0149X issue: 7
IECEX SIR 11.0150X issue: 5	IECEX SIR 11.0150X issue: 6	IECEX SIR 11.0150X issue: 7
IECEX SIR 11.0150X issue: 8	IECEX SIR 11.0150X issue: 9	IECEX SIR 12.0040X issue: 5
IECEX SIR 12.0040X issue: 6	IECEX SIR 12.0040X issue: 7	IECEX SIR 15.0118X issue: 1
IECEX SIR 17.0049X issue: 1	IECEX SIR 17.0049X issue: 2	IECEX SIR 18.0013X issue: 1
IECEX SIR 18.0017X issue: 0	IECEX SIR 18.0017X issue: 1	IECEX SIR 18.0018X issue: 0
IECEX SIR 18.0018X issue: 1	IECEX TUN 12.0001X issue: 4	IECEX TUN 12.0028X issue: 4
IECEX TUN 12.0028X issue: 5	IECEX TUN 17.0023X issue: 0	IECEX TUN 17.0023X issue: 1
IECEX TUN 17.0023X issue: 2	IECEX TUN 17.0023X issue: 3	IECEX TUN 17.0023X issue: 4
IECEX TUN 17.0023X issue: 5	IECEX TUN 17.0023X issue: 6	IECEX TUN 20.0005X issue: 0
IECEX UL 13.0029X issue: 4	IECEX UL 13.0029X issue: 5	IECEX UL 13.0029X issue: 6
IECEX UL 21.0104X issue: 0	IECEX UL 22.0060X issue: 0	IECEX UL 23.0044X issue: 0
IECEX ULD 17.0044X issue: 0	IECEX ULD 17.0044X issue: 1	IECEX ULD 18.0006X issue: 0
IECEX ULD 20.0010X issue: 0	IECEX ZLM 11.0002U issue: 2	IECEX ZLM 11.0002U issue: 3
IECEX ZLM 11.0003X issue: 2	IECEX ZLM 11.0003X issue: 3	IECEX ZLM 11.0008X issue: 1

Comments: