

Index of Component Maintenance Manuals

Ref : INDCMM-26-F4885

Rev:

February 2025



Part Number(s)	Aircraft Type	ATA Reference	Issue Date	Revision
BTCG01	TEST EQUIPMENT	GEM	June 15th 1979	-
BTCG02	TEST EQUIPMENT	GEM	September 30th 1981	-
BTCG03	TEST EQUIPMENT	GEM	April 15th 1981	-
BTCG05	TEST EQUIPMENT	GEM	June 14th 2001	-
BTCG07	TEST EQUIPMENT	GEM	November 15th 2001	-
GMC21 Airflow Bench	TEST EQUIPMENT	GEM	January 15th 2018	First issue
BTCG08	TEST EQUIPMENT	GEM	February 15th 2011	1
CTT00-00	TEST EQUIPMENT	GEM	February 1st, 2025	Rev 1
RCG9-02-00 ; RCG9-02-01 ; RCG9-03-00 ; RCG9-03-01 ; RCG9-04-00 ; RCG9-04-01 ; RCG9-04-03 ; RCG9-08-00 ; RCG9-08-01 ; RCG9-09-00 ; RCG9-09-01 ; RCG9-10-00 ; RCG9-10-01 ; RCG9-10-02 ; RCG9-10-03 ; RCG9-11-00 ; RCG9-11-01 ; RCG9-11-03 ; RCG9-11-04 ; RCG9-12-01	A300 B2/B4 ; A300 FCC ; B707 AWACS	CMM 26-11-13	July 7th 2011	10
CG7GD1 ; CG7GE ; CG7GF ; CG7GF-10 ; CG7GFSG ; CG7PD1 ; CG7PE ; CG7PF ; CG7PF-10	A300 B2/B4 ; B707 AWACS	CMM 26-11-14	April 15th 1993	6
CG7GO ; CG7GO-10 ; CG7GO-11 ; CG7GOS ; CG7PO	A300-600/A310 ; A320/321 ; ATR42/ATR72	CMM 26-11-15	September 30th 1999	5
CG7GT-10 ; CG7PT-10 ; CG7PT-2	FOKKER 50/70/100 ; BAe/Jetstream 41	CMM 26-11-16	February 1999	5
RCGSK10-00 ; RCGSK10-01 ; RCGSK10-02	A300-600/A310	CMM 26-11-17	January 15th 1993	3
AI30 ; AI30-10 ; DJ1191 FTA715 ; FTA716 ; FTA 717/718 FTA 719-XX/720-XX TRA72-2X ; TRA72-6X ; TRA73-60	ALL	CMM 26-11-18	July 1st 2020	8
RCGSK10-03 ; RCGSK10-04 ; RCGSK10-05	A300-600/A310	CMM 26-11-19	August 31st 2000	1
SD2001 ; SD2004 ; SD2005	A310 Polaris ; A300 B2F/B4F	CMM 26-11-20	March 30th 1999	2
CGAB12XX-YY ; CGAB11XX-YY ; CGFT11XX-YY	SAAB 340/2000 ; FOKKER 100 ; ALL	CMM 26-11-21	March 1st 2024	6
CGAB14XX-YY ; CGFT13XX-YY	ALL	CMM 26-11-22	March 25th 2009	6
595-002	A300 B2F/B4F	ACMM 26-11-23	May 15th 1999	-
595-014-780	A300 B2F/B4F	ACMM 26-11-24	May 15th 1999	-
FSD2100-00 ; FSD2200-00	A300 B2F/B4F A310 Polaris / A310 GAF	CMM 26-11-25	April 14th 2003	1
CCP700-00 ; CCP701-00	B767-200SF/300SF	CMM 26-11-31	Jan 3rd 2006	1
CCP800-00	B737-400SF	CMM 26-11-37	Oct 29th 2008	0
GAI2820-XX ; PAI2810-XX ; PAI2820-XX ; PAI2840-XX	A330/A340	CMM 26-16-15	May 31st 1996	3
GPA1100-00 ; GPA1101-00 ; GPA1102-00 ; GPA1103-00 ; GPA1200-00 ; GPA1201-00 ; GPA1202-00 ; GPA1203-00 ; PPA1100-00 ; PPA1101-00 ; PPA1102-00 ; PPA1103-00 ; PPA1200-00 ; PPA1201-00 ; PPA1202-00 ; PPA1203-00 ; PPA1204-00 ; PPA2100-00 ; PPA2101-00	A320 ; A330/A340	CMM 26-16-16	February, 1st, 2025	10
GPA1104-01 ; GPA1204-01 ; PPA1104-01 ; PPA1205-01 ; PPA2102-01	A320 ; A330/A340	CMM 26-16-26	February, 1st, 2025	3
CGAB2001-00 ; CGDU2000-00 ; CGDU2200-00	A300-600/A310 ; A318/A319/A320/ A321 ; ATR42/ATR72	CMM 26-16-17	March 25th 2009	6
CGFT2100-00 ; CGFT2300-00 ; CGAB2010-00 ; CGAB2020-00	ALL	CMM 26-16-18	September 15th 2004	1
PAI2800-XX ; GAI2800-XX ; PAI2830-XX	A320/A321	CMM 26-17-15	July 15th 1998	7
PAPE2800-XX	A321	CMM 26-17-17	August 31st 1994	-
PPC1100-00 ; PPC1200-00	A318/A319/A320/A321	CMM 26-18-18	February 1st, 2025	8
GMC11XX-YY ; PMC11XX-YY ; PMC31XX-YY	A330 ; A380	CMM 26-18-38	February 1st, 2025	8
CAN SDC01P05-07 ; CAN SDC01P05-09	B747	CMM 26-18-47	July 31st 2007	0
GMC2100-00-00 ; PMC2100-01-00 ; PMC2200-00-00 ; PMC2300-00-00	A350	CMM 26-16-55	February 1st, 2025	4
CSDM1001-00 ; CSDM2000-00	A350	ACMM 26-16-56	December, 1st, 2021	4
CGDU3000-00	A300-600/A310 ; A318/A319/A320/ A321 ; ATR42/ATR72	CMM 26-18-17	February 1st, 2025	2
SDCP10-00 ; SDCP20-00	A330	CMM 26-18-48	December, 1st, 2021	1

Index of Service Bulletins

Ref : INDSB-26-F4885

March 2024



Service Bulletin	Pre Mod → Post Mod	Issue Date	Revision
595009-26-001	595-009 Amdt B → FSD2200-00	April 04	1
CGAB11-26-001	Commercial modification	July 2008	4
CGAB12-26-004	CGAB1201-01 → CGAB1201-01 Amdt A	January 2004	0
CGAB12-26-004	Introduction of CGAB1201-01 Amdt A	January 2004	0
CGAB12-26-03	Introduction of CGAB1201-01	March 1999	0
CGAB14-26-001	Commercial modification	March 2008	2
CGFT11-26-001	Commercial modification	September 2008	1
FSD2005-26-001	FSD2005-00 → FSD2100-00	June 2004	1
GMC-26-001	GMC1102-02 reliability improvement	April 2016	0
KTA2400-26-003	FTA715-00 → FTA719 FTA716-00 → FTA720 FTA717-00 → FTA719 FTA718-10 → FTA720	August 1999	0
KTA2400-26-004	FTA719-00 → FTA719-01 FTA720-00 → FTA720-01 FTA720-10 → FTA720-11	March 2001	0
KTA2400-26-005	FTA717 → FTA719-01 FTA717 Amdt A → FTA719-01 FTA719-00 → FTA719-01	June 2001	0
PMC21-26-001	PMC2100-01-00 reliability improvement	May 2016	0
PMC-26-001	PMC1102-02 and PMC3100-00 reliability improvement	September 2014	0
PMC-26-002	PMC1102-02 reliability improvement	January 2016	0
PMC-26-003	FIRE PROTECTION - SMOKE DETECTOR Multicriteria Series Humidity Sensors potting issue	March 2019	1
PPA-26-003	PPA1202-00 → PPA1203-00	January 2008	1
PPAGPA-26-002	PPA1101-00 → PPA1102-00 PPA1201-00 → PPA1202-00 GPA1101-00 → GPA1102-00	February 2005	1
PPAGPA-26-004	PPA1102-00 → PPA1103-00 PPA1203-00 → PPA1204-00 GPA1102-00 → GPA1103-00 GPA1202-00 → GPA1203-00 PPA2100-00 → PPA2101-00	October 2017	3
PPC-26-001	PPC1100-00 Amdt A → Amdt B	March 2021	1
RCG9-26-1	RCG9 electronic modification	June 1978	0
RCG9-26-3	Introduction of RCG9-08-01 Amendment "A"	July 2011	0
SB-RCG-26-2	All RCG9&RCGSK type units	March 1981	/

Service Information Letter	Part Number(s)	Subject	Issue Date	Revision
SIL-26-callBPPAGPA	PPA11XX-XX, PPA12XX-XX, GPA11XX-XX, GPA12XX-XX	Introduction of a new calibration kit.	February, 2004	0
CG7-26-3	CG7GD1, CG7PD1	Phasing out of PIN CG7PD1 and CG7GD1. Retrofit of these PINs by PIN CG7PF and CG7GF	December, 2004	9
CG/ALL-26-1	All	New cleaning procedure to cope with the latest environmental and health regulations.	June, 1994	0
CG/A320-26-2	A320 Smoke Detection System	List of main fault messages, possible causes and improvement status.	June, 1994	0
CG/FTA-26-2	FTA 715, FTA 716, FTA 717, FTA 718	Phasing out of ionization smoke detectors. Introduction of smoke detectors PIN FTA719, FTA720.	December, 1998	0
SIL-26-A320-PPAGPA	PAI2800-01, PAI2830-00, GAI2800-02	Phasing out of ionization smoke detectors. Introduction of smoke detectors PIN PPA1100-00 and PPA1200-00	February, 2011	2
SIL-26-A330/A340-PPAGPA	PAI2840-01, PAI2820-01 AND GAI2820-01	Phasing out of ionization smoke detectors. Introduction of smoke detectors PIN PPA1103-00, PPA1204-00 and GPA1203-00	February, 2011	3
SIL-26-ATR-CGDU22	CG7GO-10	Phasing out of ionization smoke detectors. Introduction of optical type smoke detectors PIN CGDU2200-00 on ATR42/ATR72	May, 2001	0
SIL-26-A320-CGDU	CG7GO	Phasing out of ionization smoke detectors. Introduction of smoke detectors PIN CGDU2000-00 in A319/A320/A321 avionics compartment.	September, 2001	0
SIL-AMI-A330A340-PPA11	PAI2840-01	Phasing out of ionization smoke detectors. Introduction of optical type smoke detectors PIN PPA1103-00	July, 2002	0
SIL-26-AMDT-CMM	All	Storage/Periodic check	September, 2002	0
SIL-26-CG7GT-10	CG7GT-10	Introduction of smoke detector PIN CGFT2300-00	September, 2003	0
SIL-26-CG7PT/GT	CG7PT, CG7GT	Introduction of S/D PIN CGAB2010-00 and CGFT2100-00	January, 2004	0
SIL-26-CG7PT2 Rev. 1	CG7PT2	Introduction of smoke detector PIN CGAB2020-00	May, 2004	1
SIL-26-A300A310-CG7	CG7GO ; CG7GO-S ; CG7GO-10 ; CG7GO-11 ; CG7PO	Phasing out of ionization smoke detectors. Introduction of smoke detectors PIN CGAB2001-00 ; CGDU2000-00 ; CGDU2200-00.	September, 2004	1
SIL-26-A330/A340-PPA21	PAI2840-01	Introduction of Heated Optical Smoke Detector PIN PPA2100-00	February 2005	0
SIL-26-New-labset-calibration-interval	Labset	extend the labset calibration from six months to twelve months	January, 2005	0
SIL-26-Scattering-Bodies	Labset LABREF-1 ; LABYET MCR	Standardization of the labset calibration interval to twelve months	January, 2005	0
SIL-26-GASKET-CGDU	CGDU2000-00 CGDU2200-00	Gaskets modification	January, 2006	0
SIL-26-PPC11	PPC1100-00	Introduction of new base plate	November, 2007	0
SIL-PPC-26-001	PPC1100-00	Modification of diode D1	February 2010	0
SIL-PPC11-26-002	PPC1100-00	Introduction of PPC amendment B	March 2021	0
SIL-26-New-Stop Adhesive ELECTROLUBE	All	Validation of new red Stop Adhesive BlocLube RED 15ML (Code: BLR 15 ML) manufactured by Electrolube.	October 2008	0
SIL-26-DSD-001	CGAB2001-00 CGDU2000-00 CGDU2200-00	Obsolescence of the electronics board CE CPE190 and CE CPE210 microcontroller	April, 2009	0
SIL-26-DSD-002	CGDU2000-00	Introduction of CGDU3000-00 an Airbus Single Aisle program	September 2014	0
SIL-26-DSD-003	CGDU2200-00	Introduction of CGDU3000-00 an ATR program	December 2014	0
SIL-26-REF8-S	Test	Introduction of a new test gas more environmental friendly.	April, 2009	0
SIL-26-Radioprotection	CG7XX-YY ; FTA715 / 716 ; FTA717 / 718 ; PAI28XX-YY ; GAI28XX-YY ; FTA72A ; F957A ; F947	Information about hazardous materials handling and transportation constraints.	December 2013	2
SIL-26-Radioprotection-ATR	CG7GO / CG7GO-10 on ATR A/C	Information about Ionization Radiation Effects	April 2016	0
SIL-26-PPA12-001	PPA1202-00	Information about smoke detector procurement	June, 2010	0
SIL FTA-26-003	FTA719-01 ; FTA720-01; CE CP6170	Introduction of amendment "A" on FTA 719 and FTA720, and new board part number.	March 2012	0
SIL Re-identification PPAGPA	PPA11XX-XX, PPA12XX-XX, PPA21XX-XX, GPA11XX-XX, GPA12XX-XX	Re-identification methodology for PPA/GPA Smoke detectors	March 2014	0
SIL RCGSK10-02 hardware configuration	RCGSK10-02	Alternative version of C2 capacitor on hardware configuration	July 2013	0
SIL-26-PPAGPA-003	PPA11XX-XX, PPA12XX-XX, PPA21XX-XX, GPA11XX-XX, GPA12XX-XX	Introduction of repair solution for Q3 & Q7 Mosfet issue	July 2019	4
SIL PMC-26-001	PMC1102-02, PMC3100-00	Additional test for detecting previous thermal channel faults	April 2014	0
SIL PMC-26-002	PMC1102-02, PMC3100-00, GMC1102-02	Information about IR LED issue on PMC-GMC series	January 2016	1
SIL PMC-26-003	PMC1102-02, STC Holder IAI	Information about IR LED issue on PMC-GMC series	February 2016	2
SIL-26-GMC21-001	GMC2100-00-00	Airflow calibration modification	February 2016	0,00
SIL-26-PPAGPA-004	PPA/GPA Series	Introduction of Alternate part numbers for PPA/GPA smoke detectors family	March 2017	0
PMCGMC-26-004-A330	GMC1102-02; PMC1102-02; PMC1103-03; PMC3100-00; PMC3101-01	Introduction of upgraded Multicriteria Smoke Detector series – A330	September 2017	0
PMCGMC-26-004-A380	GMC1102-02; PMC1102-02; PMC1103-03; PMC3100-00; PMC3101-01	Introduction of upgraded Multicriteria Smoke Detector series – A380	September 2017	0
SIL-26-SIEMENS-PREVENTIVE-MAINTENANCE	All Siemens optical Smoke Detectors	Preventive maintenance for Siemens smoke detectors in pressurized areas	February 2018	0
SIL-26-GMC11-001	GMC1102-02; GMC1103-02	Procurement of the defective disk	September 2019	0
SIL-26-Optical Scattering Body	All Siemens optical Smoke Detectors	Update of single optical scattering body	February 2021	0
SIL-PMC-26-004	PMC1103-03; PMC1104-03; PMC3101-01; PMC3102-01; PMC2300-00-00	Component repair on humidity sensor	March 2024	0

Index of Component Software Revisions

Ref : INDSOFT-26-F4885

March 2024



Software Reference	Version	Interface	Concerned Products	Issue Date
IHM2	3.3	BTCG07	CGAB1100, CGAB1400, CGAB2001, CGAB2010, CGAB2020, CGDU2000, CGDU2200, CGFT1100, CGFT2100	08/12/2006
IHM3	3.3	BTCG08-XX	PPC1100, PPC1200	17/12/2020
IHM4	3.3	BTCG08-XX	PMC11XX-YY, GMC11XX-YY, PMC31XX-YY	07/01/2016
IHM5	1.0	BTCG08-XX	CGDU3000-00	28/06/2017
FSD_SwT Test environment	3.2	N/A	PMC2100-01-00 ; PMC2200-00-00 ; PMC2300-00-00 ; GMC2100-00-00 ; CSDM1001-00; CSDM2000-00	01/01/2016
FSD_SwT Test Package	3.4	N/A	PMC2100-01-00 ; PMC2200-00-00 ; PMC2300-00-00 ; GMC2100-00-00 ; CSDM1001-00; CSDM2000-00	01/05/2016
Calib Utility	3.00	CALIB PPAGPA	PPA/GPA series	30/08/2017