



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/SIR/QAR07.0039/12	Page 1 of 2
QAR Free Ref. No.:	80168463 / 80168464 / 80168465	Status: Issued
Details of change:	Recertification Audit	Date of issue: 2023-07-14
Location(s) audited:	Siemens Canada Limited 1954 Technology Drive Peterborough Ontario K9J 6X7 Canada	Valid until: 2026-07-16 Audit date: 2023-06-22
	Siemens Sensors and Communication Limited 117 GuangXian Road, QixianLing High-Tech Industrial Zone Dalian 116023 Liaoning Province China	
	Siemens SAS DI PA MF-H 1 Chemin de la Sandlach Haguenau Cedex 67506 France	
Issuing ExCB:	CSAE - CSA Group Testing UK Ltd	
Manufacturer:	Siemens Canada Limited 1954 Technology Drive Peterborough Ontario K9J 6X7	
Location of Manufacturer:	Canada	
Product information:	Instrumentation, Measurement & Control Equipment. Sensors, Transducers & Signalling Devices. Product range includes: Sitrans LR200 Probe LR Sitrans LR250	
Type of protection:	Ex ia, d, e, m, t, h & Op is	
Related QARs:		
GB/SIR/QAR07.0039/00	GB/SIR/QAR07.0039/01	GB/SIR/QAR07.0039/02
GB/SIR/QAR07.0039/03	GB/SIR/QAR07.0039/04	GB/SIR/QAR07.0039/05
GB/SIR/QAR07.0039/06	GB/SIR/QAR07.0039/07	GB/SIR/QAR07.0039/08
GB/SIR/QAR07.0039/09	GB/SIR/QAR07.0039/10	GB/SIR/QAR07.0039/11
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX BVS 11.0072 issue: 0	IECEX BVS 11.0072X issue: 1	IECEX BVS 12.0012 issue: 0
IECEX BVS 12.0012X issue: 1	IECEX BVS 12.0015 issue: 0	IECEX BVS 12.0015X issue: 1
IECEX BVS 17.0069 issue: 0	IECEX BVS 17.0069 issue: 1	IECEX BVS 18.0030 issue: 0
IECEX BVS 18.0030X issue: 1	IECEX BVS 18.0038X issue: 1	IECEX BVS 18.0038X issue: 2
IECEX CML 18.0155X issue: 0	IECEX CML 21.0058X issue: 0	IECEX CML 21.0058X issue: 1

-- Continued on the next page



IECEX Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR07.0039/12**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEX CML 21.0122X issue: 0	IECEX CML 21.0122X issue: 1	IECEX CSA 17.0015X issue: 0
IECEX CSA 17.0015X issue: 1	IECEX CSA 17.0026X issue: 0	IECEX CSA 17.0026X issue: 1
IECEX CSA 17.0026X issue: 2	IECEX DEK 11.0067X issue: 0	IECEX DEK 19.0069X issue: 0
IECEX DEK 19.0070X issue: 0	IECEX DEK 19.0070X issue: 1	IECEX DEK 19.0070X issue: 2
IECEX FMG 13.0016X issue: 1	IECEX FMG 13.0016X issue: 2	IECEX FMG 13.0016X issue: 3
IECEX KEM 09.0011X issue: 0	IECEX KEM 09.0011X issue: 1	IECEX KEM 09.0011X issue: 2
IECEX PTB 04.0013X issue: 1	IECEX PTB 08.0010X issue: 1	IECEX PTB 08.0010X issue: 2
IECEX PTB 08.0010X issue: 3	IECEX PTB 10.0067X issue: 1	IECEX PTB 16.0024X issue: 0
IECEX PTB 17.0020X issue: 0	IECEX PTB 18.0046X issue: 0	IECEX PTB 18.0046X issue: 1
IECEX SIR 05.0031X issue: 3	IECEX SIR 05.0031X issue: 4	IECEX SIR 05.0031X issue: 5
IECEX SIR 05.0031X issue: 6	IECEX SIR 05.0031X issue: 7	IECEX SIR 05.0031X issue: 8
IECEX SIR 05.0031X issue: 9	IECEX SIR 05.0031X issue: 10	IECEX SIR 05.0031X issue: 11
IECEX SIR 05.0031X issue: 12	IECEX SIR 05.0031X issue: 13	IECEX SIR 05.0031X issue: 14
IECEX SIR 05.0031X issue: 15	IECEX SIR 05.0031X issue: 16	IECEX SIR 06.0058X issue: 2
IECEX SIR 07.0090X issue: 0	IECEX SIR 07.0090X issue: 1	IECEX SIR 07.0090X issue: 2
IECEX SIR 08.0070X issue: 0	IECEX SIR 08.0070X issue: 1	IECEX SIR 08.0070X issue: 2
IECEX SIR 08.0070X issue: 3	IECEX SIR 08.0071X issue: 0	IECEX SIR 08.0071X issue: 1
IECEX SIR 08.0107X issue: 1	IECEX SIR 08.0107X issue: 2	IECEX SIR 08.0107X issue: 3
IECEX SIR 08.0107X issue: 4	IECEX SIR 08.0107X issue: 5	IECEX SIR 08.0107X issue: 6
IECEX SIR 08.0107X issue: 7	IECEX SIR 08.0107X issue: 8	IECEX SIR 08.0107X issue: 9
IECEX SIR 08.0107X issue: 10	IECEX SIR 08.0107X issue: 11	IECEX SIR 08.0107X issue: 12
IECEX SIR 08.0107X issue: 13	IECEX SIR 09.0005X issue: 0	IECEX SIR 09.0005X issue: 1
IECEX SIR 09.0005X issue: 2	IECEX SIR 09.0005X issue: 3	IECEX SIR 09.0005X issue: 4
IECEX SIR 09.0005X issue: 5	IECEX SIR 09.0073 issue: 0	IECEX SIR 09.0073 issue: 1
IECEX SIR 09.0073 issue: 2	IECEX SIR 09.0073 issue: 3	IECEX SIR 09.0148X issue: 0
IECEX SIR 09.0148X issue: 1	IECEX SIR 09.0148X issue: 2	IECEX SIR 09.0148X issue: 3
IECEX SIR 09.0148X issue: 4	IECEX SIR 09.0148X issue: 5	IECEX SIR 09.0148X issue: 6
IECEX SIR 09.0148X issue: 7	IECEX SIR 09.0148X issue: 8	IECEX SIR 09.0148X issue: 9
IECEX SIR 09.0148X issue: 10	IECEX SIR 09.0149X issue: 0	IECEX SIR 09.0149X issue: 1
IECEX SIR 09.0149X issue: 2	IECEX SIR 09.0149X issue: 3	IECEX SIR 09.0149X issue: 4
IECEX SIR 09.0149X issue: 5	IECEX SIR 09.0149X issue: 6	IECEX SIR 09.0149X issue: 4
IECEX SIR 11.0153X issue: 1	IECEX SIR 11.0153X issue: 2	IECEX SIR 11.0153X issue: 0
IECEX SIR 11.0153X issue: 4	IECEX SIR 11.0167X issue: 0	IECEX SIR 11.0153X issue: 3
IECEX SIR 13.0005X issue: 0	IECEX SIR 13.0005X issue: 1	IECEX SIR 11.0167X issue: 1
IECEX SIR 13.0006X issue: 1	IECEX SIR 13.0006X issue: 2	IECEX SIR 13.0006X issue: 0
IECEX SIR 13.0006X issue: 4	IECEX SIR 13.0007X issue: 0	IECEX SIR 13.0006X issue: 3
IECEX SIR 13.0007X issue: 2	IECEX SIR 13.0007X issue: 3	IECEX SIR 13.0007X issue: 1
IECEX SIR 13.0008X issue: 0	IECEX SIR 13.0008X issue: 1	IECEX SIR 13.0007X issue: 4
IECEX SIR 13.0009X issue: 0	IECEX SIR 13.0009X issue: 1	IECEX SIR 13.0008X issue: 2
IECEX SIR 13.0010X issue: 0	IECEX SIR 13.0010X issue: 1	IECEX SIR 13.0009X issue: 2
IECEX SIR 15.0118X issue: 0	IECEX SIR 15.0118X issue: 1	IECEX SIR 13.0010X issue: 2
IECEX SIR 18.0013X issue: 1	IECEX TUN 13.0006X issue: 0	IECEX SIR 18.0013X issue: 0
IECEX TUN 13.0020X issue: 0	IECEX TUN 13.0021 issue: 0	IECEX TUN 13.0019X issue: 0
IECEX TUN 16.0037X issue: 1	IECEX TUN 16.0038X issue: 0	IECEX TUN 16.0037X issue: 0
IECEX TUN 16.0042X issue: 0	IECEX TUN 16.0042X issue: 1	IECEX TUN 16.0039X issue: 0
IECEX TUN 16.0044X issue: 0	IECEX TUN 16.0045X issue: 0	IECEX TUN 16.0043X issue: 0
IECEX TUN 17.0010 issue: 0	IECEX TUN 17.0010X issue: 1	IECEX TUN 16.0045X issue: 1
IECEX TUN 17.0023X issue: 4	IECEX TUN 17.0023X issue: 5	IECEX TUN 17.0023X issue: 3
IECEX TUR 14.0002X issue: 0	IECEX TUR 14.0003X issue: 0	IECEX TUN 20.0001X issue: 0
IECEX TUR 14.0005X issue: 0	IECEX TUR 14.0006X issue: 0	IECEX TUR 14.0004 issue: 0
IECEX TUR 14.0031X issue: 1	IECEX TUR 14.0032 issue: 0	IECEX TUR 14.0031 issue: 0
IECEX ZLM 11.0002U issue: 3	IECEX ZLM 11.0003X issue: 2	IECEX ZLM 11.0002U issue: 2
IECEX ZLM 11.0008X issue: 1		IECEX ZLM 11.0003X issue: 3

Comments: also refer related QAR: AU/TSA/QAR06.0005/00